2018 BOND IMPROVEMENTS*



Lakewood Articulation Area

	Buildre	Enterlity on	ane ploteid	a biidirojnii	eilot Granifi	sconnodi	20 dula	dinos lod	updates office		Jedace Jedace	efficient wind	one of the distribution of	ndorenents nterot paint	Jedate h	ng dinci	m:	or window sills and the steelid	linish Litopoleete	keiot Lialkiteleni Paking!	ndodenenés	mprovement	de Liidrent le la	ald differ on the second	oordile pariii	ors districts	neted the his	d de ding de
Belmar Elementary						•	•	•	•		•	•	•	•				•	•	•	•	•	•			•		
Creighton Middle							•	•		•	•			•	•					•			•			•		
Eiber Elementary						•	•	•			•	•	•	•	•		•	•	•	•	•	•			•	•	•	•
Glennon Heights Elementary						•					•			•							•	•	•		•	•	•	
Lakewood High				•				•			•			•	•			•					•			•		•
Slater Elementary						•	•	•			•			•	•					•			•		•	•	•	
South Lakewood Elementary							•	•						•						•		•	•			•		•

*Based on 2018 Capital Improvement Plan. Subject to project scope.

Creighton Middle School Improvements

- Update security cameras & classroom security door hardware.
- Secure building vestibules, entries & office location.
- New, more secure & energy-efficient windows.
- Update existing technology for student learning.
- Parking lot improvements, sidewalk replacements.
- Update old electrical wiring, panels & increase capacity.
- Update old heating & cooling equipment, plumbing fixtures & piping.
- · Replace interior lighting with energy-efficient LEDs.
- Replace old carpet & floor tile.



Age of Facility: 56 years (built in 1962)

Square Footage: 120,847

Enrollment: 636

BUILDING CONDITION: GOOD

FCI: 6.5%

FCI is a measurement of the physical condition of the school's interior, exterior & grounds.

> Good: less than 10% Fair: 11% to 30% Poor: greater than 30%.