

# 2018 BOND IMPROVEMENTS\*



## Alameda Articulation Area

	Build new facility on same property	Expand with addition	Remodel building interior	Additions/renovations for programs	Growth accommodations	Remove modular buildings	Security camera & lock updates	Secure entries & office locations	New, more secure exterior doors	More secure & energy-efficient windows	Update existing technology	Landscaping & field improvements	Update interior paint, wall-coverings	Update electrical wiring & increase capacity	Update HVAC, plumbing & piping	Update caulk, trim & window sills	Repair & update exterior finish	New paint to protect exterior	Commercial kitchen improvements	Parking lot & sidewalk improvements	Replace old playground improvements	Replace old playground equipment	Replace old furniture	Replace old carpet & floor tile	Replace movable partitions	Replace old sinks, cabinets & shelving	Replace interior lighting with LEDs	Replace worn roofing
Alameda International Jr./Sr. High		•	•	•		•	•	•		•	•		•	•					•		•	•		•	•			
Deane Elementary			•				•	•	•	•			•							•				•	•	•	•	
Emory Elementary							•	•		•			•	•							•	•			•	•	•	
Lasley Elementary							•	•		•			•	•						•			•		•	•	•	•
Patterson International Elementary							•	•	•	•			•	•				•		•					•	•		
Rose Stein International Elementary							•	•											•									

\*Based on 2018 Capital Improvement Plan. Subject to project scope.

### Patterson International Elementary School Improvements

- Update security cameras & classroom security door hardware.
- Secure building vestibules, entries & office location.
- New, more secure exterior doors.
- New, more secure & energy-efficient windows.
- Update existing technology for student learning.
- Update old electrical wiring, panels & increase capacity.
- Update old heating & cooling equipment, plumbing fixtures & piping.
- Commercial kitchen improvements.
- Replace:
  - Old playground equipment;
  - Old sink cabinets, overhead shelving & bookcases;
  - Interior lighting with energy-efficient LEDs;
  - Old ceilings; &
  - Worn roofing.



Age of Facility: 54 years (built in 1964)  
Square Footage: 48,895

Enrollment: 347

**BUILDING  
CONDITION:  
POOR**

**FCI: 35.1%**

FCI is a measurement of the physical condition of the school's interior, exterior & grounds.

Good: less than 10%  
Fair: 11% to 30%  
Poor: greater than 30%.

Estimated cost of proposed improvements: \$2,119,131. Subject to change per final project scope.