2018 BOND IMPROVEMENTS*



Wheat Ridge Articulation Area

	Buildre	topadi topadi	me propered	a building inte	ziot Gowin	COUNT.	arodular buik	jing, 1904,	ities doffice	ocalidas Resecute exe	44	elficient windown	of field in	indioderients interior paint.	wall-coverings alectrical with	od Wilder	zakačity od opinos od od opinos od od opinos od od opinos od o	Anindon siles An	linish Litopideete	Areiot Josephing V	ndojenenti ot ^o identi	indrate nents	edulphient ledulphient led funiture Replace	Jd albert of a	oorijie Redikte fatiit	ne pedace	nets disternish the state of th	d grant LED's gran
Everitt Middle							•	•			•		•	•	•					•			•		•	•		
Kullerstrand Elementary						•	•	•			•		•	•	•							•	•		•	•	•	•
Maple Grove Elementary									•	•	•			•	•					•		•	•			•		
Peak Expeditionary School at Pennington							•	•			•		•	•	•								•		•	•		•
Prospect Valley Elementary	•																											
Stevens Elementary							•	•			•			•	•											•		•
Stober Elementary						•	•	•	•	•	•		•	•	•				•	•	•	•	•		•	•	•	•
Vivian Elementary						•	•	•			•			•	•								•		•	•		
Wheat Ridge High			•	•			•	•			•	•		•	•								•	•	•	•	•	•
Wilmore-Davis Elementary			•				•	•	•		•			•	•						•	•	•	•	•	•	•	•

*Based on 2018 Capital Improvement Plan. Subject to project scope.

Stober Elementary School Improvements

- New interior finishes such as: new carpet, new tile flooring, paint entire interior, replace ceiling throughout, new energy-efficient windows & exterior doors, new interior doors & hardware, bathroom renovations & removal of asbestos floor tile.
- New cabinets & cases, including art & music spaces.
- Replace furniture, desks & classroom fixtures.
- Reconfigure office to improve entrance line of sight, safety & security.
- · Construction of secure entrance vestibule.
- Install an elevator & shaft.
- Install modern & energy efficient lighting.
- Replace building electrical system to support increased use of electrical devices.
- Upgraded fiber systems, routers & other Internet systems to support 1:1 devices & high speed access.

- Kitchen remodel & redesign (convection oven, steamer, hood, wall & floor finishes).
- Complete heating, ventilation, air-conditioning system replacement.
- Partial roof replacement (roof was replaced due to hail damage, but partial roof replacement is needed to remove & replace old HVAC systems).
- Redesign & repave parking & driveways to enhance pedestrian access, improve traffic flow, & assure ADA compliance.
- New playgrounds & fall-zone material.
- Remove temporary buildings & reclamation of those areas.



Age of Facility: 53 years (built in 1965)

Square Footage: 31,243

Enrollment: 277

BUILDING CONDITION: POOR

FCI: 56.1%

FCI is a measurement of the physical condition of the school's interior, exterior & grounds.

> Good: less than 10% Fair: 11% to 30% Poor: greater than 30%.