2018 BOND IMPROVEMENTS*



Columbine Articulation Area

	Buildre	enterlity on	arie diodeth	albilding interior	or Godin	s for ploglatic sconmodali	odnje	ame.	xies	oci exei	Jeddoofs Jeddoofs	elicient mind elicient mind elicient minde	out Update	ndicherents ndicher pant	wall-covering to the late of t	ug inc.	abaith a shirth	spindowialle ophile exterior finish the Apint to Order	eterior Patriol	notolehelis	ndovernents	Sedulphent Sedulphent Replace	Jd called on a	oordie pariit	Sid sints lati	nete de telanich nete de telanich nete de telanich	d dutification of the state of
Columbine High		•	•	•			•	•	•		•	•	•	•	•		•	•			•	•		•	•	•	
Columbine Hills Elementary							•	•			•			•	•			•	•	•		•			•	•	•
Dutch Creek Elementary							•	•			•	•		•	•		•	•		•		•	•	•	•		
Governor's Ranch Elementary							•	•		•	•		•	•	•			•		•		•			•	•	
Ken Caryl Middle							•	•	•		•		•	•	•			•				•	•	•	•	•	
Leawood Elementary							•	•			•		•	•	•			•		•		•		•	•	•	
Normandy Elementary						•	•	•			•		•	•	•	•		•	•	•		•		•	•	•	•

*Based on 2018 Capital Improvement Plan. Subject to project scope.

Columbine High School Improvements

- Expand facility with an addition.
- Remodel of building interior.
- Improvement to landscaping & athletic fields.
- Repair & update exterior finish.
- · Update security cameras & classroom security door hardware.
- · Secure building vestibules, entries & office
- · Update existing technology for student learning.
- Update old electrical wiring, panels & increase
- · Update old heating & cooling equipment, plumbing fixtures & piping.

- · New paint to protect exterior.
- Construction of auxiliary gym.
- · Renovation of locker rooms.
- Old student furniture, cafeteria tables & library furniture;
- Old sink cabinets, overhead shelving &
- Old ceilings. Update interior paint, wall-
- Interior lighting with energy-efficient LEDs; &
- Old carpet & floor tile.



Age of Facility: 45 years (built in 1973) Square Footage: 238,149

Enrollment: 1,691

BUILDING CONDITION: FAIR

FCI: 21%

FCI is a measurement of the physical condition of the school's interior, exterior & grounds.

> Good: less than 10% Fair: 11% to 30% Poor: greater than 30%.