2018 BOND IMPROVEMENTS*



Chatfield Articulation Area

	Build ne	an lacility on Si	ine plopeth	al billdird into	VELO .	sconnoditi	Modulia.	amera & lock	ntries & Othic	ocations research	iot doors	plefficient and been been been been been been been be	out of the difference of the d	Refore Rents	arall covering	ng dincre abin	:(1)	white extending to potential to the control of the	keiod Lialkitelenid	ndrolenells	ndoverhent	ediforent led furifule Replace of	d dane of the land	or the partie	nt Replace	nete de stavinod nete de stavinod nete de stavinod	gelinds Reddectoric
Bradford K-8 North							•	•			•			•					•	•		•			•		
Bradford K-8 South							•	•			•			•	•					•		•			•		
Chatfield High			•	•			•	•			•	•		•	•		•				•	•		•	•		
Coronado Elementary			•				•	•			•			•	•			•		•	•	•	•	•	•	•	
Deer Creek Middle							•	•			•		•	•	•							•	•	•	•	•	
Falcon Bluffs Middle							•	•			•		•	•	•				•			•			•		
Mortensen Elementary							•	•			•			•								•	•				
Shaffer Elementary						•	•	•			•			•	•					•		•	•		•		
Stony Creek Elementary						•	•	•			•			•	•					•	•	•		•	•	•	
Ute Meadows Elementary						•	•	•			•		•	•	•						•		•	•	•	•	

 * Based on 2018 Capital Improvement Plan. Subject to project scope.

Ute Meadows Elementary School Improvements

- Remove modular buildings.
- Update security cameras & classroom security door hardware.
- Secure building vestibules, entries & office location.
- Update existing technology for student learning.
- Update interior paint, wall-coverings.
- Update old electrical wiring, panels & increase capacity.
- Update old heating & cooling equipment, plumbing fixtures & piping.

- Replace
 - Old student furniture, cafeteria tables & library furniture.
 - Old sink cabinets, overhead shelving & bookcases;
 - Movable partitions with new, sound-proof models:
 - Interior lighting with energy-efficient LEDs: &
 - Old ceilings.



Age of Facility: 31 years (built in 1987)

Square Footage: 46,466

Enrollment: 370

BUILDING CONDITION: FAIR

FCI: 19.4%

FCI is a measurement of the physical condition of the school's interior, exterior & grounds.

> Good: less than 10% Fair: 11% to 30% Poor: greater than 30%.