2018 BOND IMPROVEMENTS*



Ralston Valley Articulation Area

						6	5					8	ous		d	5 c	apacitol	:115			.6	X ⁶	° &				ir	9
		w _e	arne property	'n.	ario ^r	s kor program	ion ⁵	ameta block	updates	ocations	or goots	efficient wind	idogy ldin	nDrovenents	wall-cove inco	ind sincted se control of the second	g & piping rime	windows in	finish octet	eriot an in	,provement.	ntroverner.	Jedlipher.	, &	oortile oatiti	ors di	mets & shelly.	gwith LEDS
	Buildne	underlied on St.	with addition of Remod	al building in	nslenovatie	accommod Remove	duis	anera do	Hies &O.	ne secure exec	Jegere Jodite	efficient existing technology	Job Jedin	nprod Daint.	alectrical a	S Ainclease of Mark Dunding	Repair & U	Politico de la Contraction de	tinish Commerci	jalkitche Parking k	Redace of	d playdi	Jediphe dd Lynighe Replace	old Carper	oorlile patiti	old sinks,	neted she hindhing in the she she she she she she she she she s	godille of the state of the sta
Coal Creek Canyon K-8							•	•		•	•			•	•						•		•			•		
Meiklejohn Elementary							•	•			•			•												•		
Oberon Middle		•	•				•	•		•	•	•		•	•										•	•	•	
Ralston Valley High		•	•	•			•	•			•	•		•	•											•		
Sierra Elementary																												
Three Creek K-8		•										•																
Van Arsdale Elementary						•	•	•			•			•	•						•	•	•			•		
West Woods Elementary							•	•			•		•	•							•	•	•			•		

*Based on 2018 Capital Improvement Plan. Subject to project scope.

West Woods Elementary School Improvements

- Replace old playground equipment.
- Update interior paint.
- Update security cameras & classroom security door hardware.
- Secure building vestibules, entries & office location.
- Update existing technology for student learning.
- Update old electrical wiring, panels & increase capacity.
- Replace interior lighting with energy-efficient LEDs.
- Replace old furniture.
- Replace old carpet & floor tile.



Age of Facility: 22 years (built in 1996)

Square Footage: 53,381

Enrollment: 743

BUILDING CONDITION: FAIR

FCI: 22.1%

FCI is a measurement of the physical condition of the school's interior, exterior & grounds.

> Good: less than 10% Fair: 11% to 30% Poor: greater than 30%.